

APPENDIX H
US RTE 1 SOUTHBOUND QUEUING
AT RTE 610

US Route 1 Photos at Route 610 Garrisonville Road Stafford County, VA

Thursday 4/11/2013 – PM Peak
by Bowman Consulting Group, Ltd.

Prepared for: Stafford County
US Route 1 Corridor Study
BCG # 9390-01-001



Garrisonville
Road

← US Rte 1 →

US Route 1 – Facing West
PM Peak – Time = 5:30 PM



Garrisonville
Road

← US Rte 1 →

US Route 1 – Facing West
PM Peak – Time = 5:33 PM



Coachman Circle
South

US Route 1 – Facing North
PM Peak – Time = 5:40 PM



Coachman Circle
South

US Route 1 – Facing North
PM Peak – Time = 5:40 PM



Coachman Circle
North

US Route 1 – Facing North
PM Peak – Time = 5:40 PM



US Route 1 – Facing North
PM Peak – Time = 5:40 PM



Coachman Circle
North

US Route 1 – Facing North
PM Peak – Time = 5:40 PM



US Route 1 – Facing North
PM Peak – Time = 5:40 PM

Coachman Circle
South



US Route 1 – Facing South
PM Peak – Time = 5:43 PM



US Route 1 – Facing South
PM Peak – Time = 5:45 PM



US Route 1 – Facing South
PM Peak – Time = 5:45 PM



Garrisonville
Road Signal

I-95 NB On-Ramp

US Route 1 – Facing South
PM Peak – Time = 5:47 PM